# EARTHQUAKE RISK MANAGEMENT IN THAILAND; CURRENT STATUS AND FUTURE IMPLICATION

#### Niran CHAIMANEE<sup>a</sup>

<sup>a</sup>Coordinating Committee for Geosciences Programmes in East and Southeast Asia, CCOP Technical Secretariat. 75/10 Rama 6 Road, Ratchathewi 10400, Bangkok, Thailand






#### **OUTLINE OF PRESENTATION**

- -- OVERVIEW OF EARTH MOVEMENT IN THAILAND
- -- ASSESSMENT OF GEOHAZARD RELATED TO EARTHQUAKE
- MONITORING AND HAZARD MAP
- -- IMPLICATION












#### VULNERABILITY OF NATURAL HAZARD IN SE ASIA

Eruption records SE Asia



Seismic map of SE Asia

Tsunami records of SE Asia






#### Summary of Natural Disasters (1991-2000)


Wild fire

4%



According to the data from typhoon which are the prominent caused by windstorm and flood a each (Fig.1-7).

Fig. 1-6



Wind storm

15%





Amount of Damage(Disaster Types)

(1,000 US\$) (Asia, 1975-2000)


Earthquake

47%

Drought


2%

#### **General Geology of Thailand**





Thailand is has been de area. Howe national seisi small- and revealed, mo general belie Moreover, si low- to mod earthquake (MMI) rang moderate da



Plate, which e seismicity ovement of of frequent have been contrast to


number of hallow-depth Intensities ng slight to






Apart from earthquakes Thailand, inside boundaries of the Indian and Australian tectonic plates and the Sunda and Burma tectonic plate are considered as zones of high seismicity, with the largest instrumentally recorded event being MS 7.8 in 1946.


Major tectonic elements in Southeast Asia and Southern China. Arrows show relative directions of motion of crustal blocks during the Late Cenozoic. MPFZ—Mae Ping Fault Zone; NTFZ—Northern Thailand Fault Zone; TPFZ—Three Pagodas Fault Zone; UFZ—Uttaradit Fault Zone. (After Ornthammarath et al. 2010)













McCloskey, J., et al. 2005. Earthquake risk from co-seismic stress. Nature Geoscience, 434: 291

We have calculated the distributions of co-seismic stress on this zone, as well as on the neighbouring, vertical strike—slip Sumatra fault, and find an increase in stress on both structures that significantly boosts the already considerable earthquake hazard posed by them. In particular, the increased potential for a large subduction-zone event in this region, with the concomitant risk of another tsunami, makes the need for a tsunami warning system in the Indian Ocean all the more urgent.

#### THAILAND'S VELOCITY






Before December 2004

(After Promthong et al., 2005)

After December 2004



#### ACCUMULATION OF ELASTIC DEFORMATION



Accumulation: hundreds, even thousands of years

**Rupture:** seconds to minutes

**Relaxation:** months to years







Displacement of Thai Geodetic Network after the Sumatra-Andaman earthquakes on December 24th 2004 up to November 2010

(Satirapod et. al., 2011)

GPS results reveal that significant vertical downlifts after the Earthquake are around 12 mm/yr @ PTC1 & CPN1, 10 mm/yr @ KMI1 and 5 mm/yr @ CMU1







## Earthquakes in Thailand-Burma-Indochina Region

**(1910-2000)** 

## THE FINAL EARTHQUAKE CATALOGUE COVERS EARTHQUAKES FROM 1912 TO 2007 IN AN AREA COVERING LATITUDES 0°N-30°N AND LONGITUDES 88°E-110°E PREPARE BY THE THAI METEOROLOGICAL DEPARTMENT.

Table 1 Sample data from the final updated earthquake catalogue

YR	МО	DA	HR	MN	SEC	Lat o	Long °	DEPTH (KM)	MS, mb, ML	Definiton	Mw	Source
1996	8	09	00	26	45.0	12.23	93.64	33	5.70	$M_L$	5.70	TMD
1996	8	09	23	24	47.0	22.60	98.00	33	4.00	$M_L$	4.00	TMD
1996	8	10	22	43	37.0	24.71	95.30	33	4.20	ть	4.60	PDE
1996	8	11	11	04	26.6	14.07	93.73	33	4.00	mь	4.43	PDE
1996	8	11	11	48	27.9	14.09	93.82	33	4.20	m <sub>b</sub>	4.60	PDE
1996	8	11	18	48	12.4	4.26	95.62	100	3.80	m <sub>b</sub>	4.26	PDE
1996	8	13	10	33	35.0	22.50	102.00	33	4.20	$M_L$	4.20	TMD
1996	8	14	16	18	51.0	21.40	99.70	33	3.20	$M_L$	3.20	TMD
1996	8	16	23	39	38.4	24.42	94.98	33	4.10	mь	4.52	PDE
1996	8	17	16	41	33.0	21.80	99.20	33	3.30	$M_L$	3.30	TMD
1996	8	20	08	30	10.9	24.12	94.99	120	4.40	$M_S$	5.02	PDE
1996	8	23	05	40	41.0	14.71	95.75	33	5.70	$M_L$	5.70	TMD
1996	8	23	18	53	07.8	21.63	99.25	33	3.30	$M_L$	3.30	TMD
1996	8	24	03	54	44.0	0.86	99.46	110	5.00	mь	5.28	PDE

Remarks: TMD Thai Meteorological Department


PDE National Earthquake Information Center, USGS)

ISC International Seismological Centre





Seismic hazard assessment of Thailand was shown as seismicity of thailand and its surrounding during 1912 - 2007



100°E

105°E

(Ornthammarath et al. 2010)









#### สรุปพื้นที่ที่มีรอยเสื่อนมีพลังพาคผ่านของประเทศไทย

ภาค	จังหวัด	อำเภอ	ตำบล	หมู่บ้าน
អេជី <sub>២</sub>	เชียงใหม่	12	35	174
เหนือ	เชียงราย	11	25	134
เหนือ	แพร่	7	22	83
เหนือ	แม่ชี่ดูงสิดูน	5	15	54
เหนือ	กำแพงเพชร	3	3	6
เหนือ	ตาก	7	20	127
เหนือ	น่าน	6	17	68
เหนือ	พะเยา	1	1	1
เหนือ	พูหญ์เลบ	2	3	7
เหนือ	ล้าปาง	5	15	37
เหนือ	ลำพูน	3	6	56
เหนือ	ยุตรติตต์	4	11	62
ใต้	กระนี่	1	2	3
តែ	มีทพง	4	16	56
តែ	พังงา	5	16	52
ใต้	ระนอง	5	14	85
ใต้	สุราษฎร์ชานี	9	24	76
กลาง	กาญจนบุรี	7	31	192
กลาง	ประจวบดีรีขันช์	4	18	79
f1871\$	สุพรรณบุรี	1	1	7
ตะวันออกเฉียงเหนือ	นคริพนม	3	8	28
ตะวันออกเฉียงเหนือ	ทนองคาย	2	5	19
23H	22	106	308	1,406


(กรมทรัพยากรธรณี, 2553)

\_11-0290(001-085).indd 37 328/11 9:45:39 PM





#### Seismicities of Northern Thailand (1912-2006)



Magnitude (Mb)

- 5.1-6.5
- 4.1 5.0
- < 4.0




#### Seismicities of Northern Thailand (1912-2006)



Magnitude (Mb)

- 5.1-6.5
- 4.1 5.0
- < 4.0

#### Seismicities of Western Thailand




Magnitude (Mb)

- 5.1-6
- 4.1 5.0
- < 4.0





#### Seismicities of Western Thailand




Magnitude (Mb)

- **o** 5.1- 6
- 4.1 5.0
- < 4.0






## Earthquake with Mb at lease 5.0 in the Vicinity of Thailand







## Earthquake with Mb at lease 5.0 in the Vicinity of Thailand












Fig. 8 Thailand hazard maps for PGA corresponding to a probability of exceedance of 10% in 50 years







#### **Current Seismic Design Code Regulation**



Effective since Nov. 1997

•Revised in 2007

Limited to 10 provinces plus

Bangkok and 4 provinces vicinity

Watch Zone of 7 provinces in the South.

Limited to public buildings, essential facilities, hazardous facilities, and structures with more than 15-m high, bridge with more than 10 m. long and dam with more than 10 m. height.


Design requirements are similar to those of the USA Standard 1985; Uniform Building Code Zone 2





#### **Limited Ductility Standard 1302**


Department of Public Work and Town & Country Planning,;200



		ความเร่งตอบสนอง (g)			
จังหวัด	อำเภอ				
	ļ	S,	$S_{i}$		
เชียงราย	กิ่งอำเภอคอยหลวง	0.924	0.270		
	กิ่งอำเภอเวียงเชียงรุ้ง	0.833	0.241		
	ขุนตาล	0.650	0.169		
	เชียงของ	0.706	0.191		
	เชียงแสน	0.935	0.273		
	เทิง	0.619	0.157		
	ป่าแคค	0.618	0.154		
	พญาเม็งราย	0.672	0.180		
	พาน	0.656	0.173		
	เมืองเชียงราย	0.798	0.232		
	แม่จัน	0.940	0.278		
	แม่ฟ้าหลวง	0.929	0.275		
	แม่ลาว	0.735	0.211		
	แม่สรวย	0.749	0.209		
	แม่สาย	0.933	0.273		
	เวียงแก่น	0.683	0.175		
	เวียงชัย	0.753	0.215		



#### Earthquake Management in Thailand




The National Earthquake Committee (13 gov. agencies and 4 expert) overlook the national policy with the Thai Department of Meteorological as the secretary of this committee.

The TDM monitor with 13 analog and 11 digital seismograph stations throughout the country. Department of Mineral Resources; 22 stations Eletricity Generating Authority of Thailand; 2 station







แผนภูมิที่ 3.1 วัฏจักรการบริหารจัดการสาธารณภัย (Disaster Management Cycle)

ที่มา : ASEAN Disaster Risk Management Course; United Nations Office for the Coordination of Humanitarian Affairs (UNOCHA)





#### Mitigat

#### **Under**



### Inform transm





ความรุมแรง	สภาพของแพ่นตินใหว	ความรุบแรง	สภาพของเพ่นดันไ
t daumn	180	VII ISUUN	61
คนธรรมดาจะไม่รู้สึก แต่เครื่องวัดสามารถ ตรวจจับได้		ฝาทั้ยงแยก ร้าว กรุเพพานร่วง	
II daunn	28	VIII rhane	THE WAY
คนที่มีความรู้สึกไว จะรู้สึกว่าแผ่นคินไหว เล็กน้อย	2 F	ค้องหฤดธับรถยนศ์ ศึกร้าว ปล่องไฟพัง	0
III an	20	IX mmugryalu	
คนที่อยู่กับที่	( 00 )	บ้านพังตามแถบ	= 160
รู้สึกว่าพื้นสั่น		รธยแยกรองแผ่นดิน ท่อน้ำ ท่อก๊าซ ชาดเป็นท่อนๆ	H.
IV wedsunu	(P)	X วินาคกัย	
คนที่สัญจรไปมา รู้สึกได้		แผ่นดินแตกอ้า ศึกแข็งแรงพัง รางรถไฟคตโค้ง ดินลาคเขาเคลื่อนตัว หรือถล่มลงมา	100
V daudrouso	, Alex 9	XI Sunefulnoj	
คนที่นอนหลับ คกใจดื่น		ดีกถล่ม สะพานชาด ทางรถไฟ ท่อน้ำและ สายไฟใต้ดินเสียทาย แผ่นดินถล่ม น้ำท่วม	1
VI ESO	G	XII umoùa	4
คันไม้สั้น บ้านแกร่ง สิ่งปลูกสร้าง บางชนิดพัง		ทุกสิ่งทุกยย่าง บนที่นถนนแถบนั้น เสียทายโดยสิ้นสิ่ง พื้นดินเคลื่อนตัว เป็นลูกคลื่น	I

รูปที่ 20 ระดับความรุนแรงของแผ่นดินไทวดามมาตราเมอร์คัดดี่ (Mercoli) มี 12 ระดับ

es

#### atory

about the isaster, preparedness

System

ient, a and Routes


\_11-0290(001-062).Indd 25

3/28/11 9:45:28 PM





### System design: End-to-end early warning (ADPC)







#### Implication

There are critical problems in countries, and need regional mechanism to support them by coordination amongst agencies and sectors e.g. scientific community and disaster management practitioners

Provide venue for countries to share knowledge and experiences

Develop guidelines to assist countries in formulating the mitigation plan based from countries' experience

Minimize damages and teach people in risk areas how to prevent themselves from disaster



